



U.S. ARMY CORPS
OF ENGINEERS

FEATHER RIVER *Fact Sheet*

PL84-99 Sites

Emergency Levee Repairs

Location

River: Feather

Site Identification #:
20051230-025-003
(Levee Mile 12.7)

Latitude/Longitude:
38.957217/-121.574933

Nearest Impact Area:
Plumas Lake

County: Yuba

Bank: Left

Type of Damage

Bank erosion

Total Length of Repair


400 feet (approximate)

Repair Type

Relief wells, lined canal

Lead Agency

Reclamation District 784



**For further information,
please contact:**

Les Schmittner
Project Manager
U.S. Army Corps of Engineers
(916) 440-2263

Lester.C.Schmittner@spk01.usace.army.mil